

Web site: www.ecotek.eu
email: help@ecotek.eu

CB-26P Fitting position

Rover 75



Rover 75 fitting from Stephan Senger - who's from Germany - where the non-return valve has been moved (originally it is placed about 8cm far away from the inlet manifold).

This makes sense if you want to fit the device (and filter in this case) near to the manifold in a place where there is enough room. Always remember to fit the CB-26P device manifold side of the non return valve.

He said:

"The performance improvement is unbelievable. My car seems to have 20 horsepower extra, it is much more torquier and drives a lot smoother."