


Web site: www.ecotek.eu
email: help@ecotek.eu

CB-26P Fitting position

Corsa 1.2 8v



The Corsa B 1.2 - 8 Valve - owned by Sam Ackers needs an Ecotek to pep up the motors performance through the gears and improve throttle response.

The MAP sensor vacuum pipe highlighted with the red dot shows where the valve can be positioned. The red dot marks the spot.

Also, most owners report that the annoying flat spot between 1500-2000 rpm on these engines disappears with the Ecotek fitted.